

Figure 31
Signs on Clark Place



Issue:

1. Traffic Operations and pavement markings at Arizona Avenue. During the PM peak hour, through traffic traveling in the left lane drives in what appears to be an oncoming lane.
2. Poor condition of street signs.

Preliminary Improvement(s):


1. Modify pavement markings and install additional lane control signals to clarify operations. Figure 32 is an aerial photograph of the intersection showing proposed lane control signals and their operation at various times of the day.
2. Replace street sign.

Evaluation:

1. As shown in Figure 32, the Arrow/"ONLY" markings on inbound Canal Road could be removed to eliminate any confusion to outbound motorists driving against the markings during the PM peak hour. Lane control signals could be hung from the trail bridge at Arizona Avenue, instructing motorists on which lanes are available to them.

Recommendation:

- Install new signs and lane control signals, and remove pavement markings as shown in Figure 32.



NOTE: Signal Heads to be installed supported from the pedestrian bridge